

HAER
CAL
26-JULA.V,
1C-

**HISTORIC AMERICAN ENGINEERING RECORD
INDEX TO PHOTOGRAPHS**

**Rush Creek Hydroelectric System,
Worker Cottage (Building 104)
Rush Creek
June Lake Vicinity
Mono County
California**

HAER No. CA-166-C

Gregory L. O'Loughlin, photographer

August, 1997

- CA-I66-C-1 EXTERIOR OVERVIEW OF SOUTH END OF RUSH CREEK POWERHOUSE RESIDENTIAL COMPLEX SHOWING THE RUSH CREEK POWERHOUSE AT PHOTO RIGHT, BUILDING 106 NEXT TO THE POWERHOUSE AT PHOTO CENTER, BUILDING 103 AT UPPER PHOTO LEFT, AND BUILDING 104 ABOVE BUILDING 106 PARTIALLY OBSCURED BEHIND TREE AT UPPER PHOTO CENTER. VIEW TO SOUTH.
- CA-I66-C-2 EXTERIOR SOUTH END OF BUILDING 104 SHOWING CONCRETE STEPS WITH METAL HANDRAIL TO HOUSE FROM POWERHOUSE AND OFFSET GABLE OVER FRONT ENTRY. VIEW TO NORTHWEST.
- CA-I66-C-3 EXTERIOR OF SOUTH END OF BUILDING 104 SHOWING PAVED VEHICLE ACCESS AND ROCK RETAINING WALL CAPPED BY METAL HANDRAIL. BOTH BASEMENT DOORS (BELOW KITCHEN WINDOWS AT PHOTO CENTER AND BELOW WOOD-SIDED BEDROOM ADDITION AT PHOTO RIGHT) ARE VISIBLE IN THIS VIEW. VIEW TO NORTH.
- CA-I66-C-4 EXTERIOR OF SOUTH END OF BUILDING 104 SHOWING 1-LIGHT SIDE EXIT DOOR AND ORIGINAL WOOD-FRAMED SLIDING-GLASS KITCHEN WINDOWS AT PHOTO CENTER, AND TALL RUSTIC STYLE CHIMNEY WITH GABLE FRAME ON BACK WALL OF HOUSE. VIEW TO NORTHEAST.
- CA-I66-C-5 EXTERIOR OF NORTH END OF BUILDING 104 SHOWING WOOD-SIDED BEDROOM ADDITION TO FRONT OF HOUSE, AND SMALL GABLE ROOF OVER FORMER BATHROOM PROJECTION ON NORTH END OF HOUSE. VIEW TO SOUTH.

RUSH CREEK HYDROELECTRIC SYSTEM
WORKER COTTAGE (BUILDING 104)
HAER No. CA-166-C
INDEX TO PHOTOGRAPHS (Page 2)

- CA-166-C-6 INTERIOR OF UNFINISHED BASEMENT UNDER BEDROOM ADDITION SHOWING CONCRETE FORM IMPRESSIONS ON THE WALLS, AND EXPOSED FLOOR SUPPORT BEAMS. VIEW TO NORTH.
- CA-166-C-7 INTERIOR OF VESTIBULE SHOWING OPEN 1-LIGHT FRONT DOOR AT PHOTO RIGHT, AND OPEN PANEL DOOR TO BEDROOM ADDITION (BEDROOM NUMBER TWO) AT PHOTO CENTER. VIEW TO WEST.
- CA-166-C-8 INTERIOR OF LIVING ROOM SHOWING OPEN DOORWAY TO KITCHEN AT PHOTO RIGHT, 6-LIGHT OVER 1-LIGHT SASH WINDOWS ON FRONT (EAST) WALL AT PHOTO CENTER. ENTRY ROOM AND OPEN 1-LIGHT FRONT DOOR AT EXTREME PHOTO LEFT. VIEW TO SOUTHEAST.
- CA-166-C-9 INTERIOR OF LIVING ROOM SHOWING OPEN PANEL DOOR TO BEDROOM NUMBER ONE AT PHOTO RIGHT, 6-LIGHT OVER 1-LIGHT SASH WINDOW ON REAR WALL AT PHOTO LEFT CENTER. FIREPLACE ORIGINALLY OCCUPIED SPACE UNDER ROUND HEATER VENT HOLE AT PHOTO LEFT. VIEW TO NORTHWEST.
- CA-166-C-10 INTERIOR OF WEST END OF BEDROOM NUMBER ONE SHOWING ORIGINAL LOCATION OF BATHROOM AND WALK-IN CLOSET. SMALL 1-LIGHT OVER 1-LIGHT SASH WINDOW AT PHOTO LEFT WAS ORIGINALLY ON BACK WALL OF CLOSET. BATHROOM PROJECTION ON NORTH WALL IS NOW OCCUPIED BY RECESSED BUILT-IN CLOSET SHOWN AT PHOTO RIGHT CENTER. VIEW TO WEST.
- CA-166-C-11 INTERIOR OF BEDROOM NUMBER ONE SHOWING OPEN PANEL DOOR TO LIVING ROOM AT PHOTO RIGHT AND OPEN DOOR TO BATHROOM AT PHOTO LEFT. VIEW TO SOUTHEAST.
- CA-166-C-12 INTERIOR OF BATHROOM LOOKING BACK INTO BEDROOM NUMBER ONE. VIEW TO WEST
- CA-166-C-13 INTERIOR OF BATHROOM SHOWING 1-LIGHT OVER 1-LIGHT SASH WINDOW ON NORTH WALL. VIEW TO NORTH.

RUSH CREEK HYDROELECTRIC SYSTEM
WORKER COTTAGE (BUILDING 104)
HAER No. CA-166-C
INDEX TO PHOTOGRAPHS (Page 3)

- CA-166-C-14 INTERIOR OF BEDROOM NUMBER TWO SHOWING FLOOR TO CEILING BUILT-IN CLOSET OCCUPING ENTIRE NORTH END OF ROOM, AND 6-LIGHT OVER 1-LIGHT SASH WINDOW ON EAST WALL. VIEW TO NORTH.
- CA-166-C-15 INTERIOR OF BEDROOM NUMBER TWO SHOWING OPEN DOOR TO VESTIBULE AT PHOTO RIGHT, AND 6-LIGHT OVER 1-LIGHT SASH WINDOW THROUGH SOUTH WALL AT PHOTO LEFT. VIEW TO SOUTH.
- CA-166-C-16 INTERIOR OF KITCHEN SHOWING UPDATED CABINETS AND COUNTER TOP, AND ORIGINAL WOOD-FRAMED SLIDING GLASS WINDOW IN NORTH WALL OVERLOOKING FRONT ENTRY. VIEW TO NORTHEAST.
- CA-166-C-17 INTERIOR OF KITCHEN SHOWING UPDATED CABINETS, SINK, AND FAUCET, AND ORIGINAL WOOD-FRAMED SLIDING GLASS WINDOWS ON SOUTH WALL OVER SINK. VIEW TO SOUTHEAST
- CA-166-C-18 INTERIOR OF KITCHEN SHOWING OPEN 6-LIGHT DOOR TO SIDE-ENTRY UTILITY ROOM AT PHOTO LEFT, AND OPEN DOOR TO WALK-IN PANTRY AT PHOTO RIGHT. VIEW TO SOUTHWEST.
- CA-166-C-19 INTERIOR OF PANTRY SHOWING SHELVES, PLUMBING FOR A SINK, AND 1-LIGHT OVER 1-LIGHT SASH WINDOW ON SOUTH WALL. VIEW TO SOUTHWEST.
- CA-166-C-20 INTERIOR OF SIDE-ENTRY UTILITY ROOM SHOWING OPEN 1-LIGHT SIDE-EXIT DOOR AT PHOTO LEFT AND 1-LIGHT OVER 1-LIGHT SASH WINDOW INTO PANTRY AT PHOTO RIGHT. VIEW TO SOUTHWEST.